व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: T-83/1379 माह/Month: May, 2022 Validity: 30.04.2029



KARNATAKA VILLAGE & AGRO INDUSTRIES KVAI 5TN TIPPING TRACTOR TRAILER



भारत सरकार

Government of India कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

Tele.: 08551-286441

Page 1 of 29

T-83/1379

Manufacturer	:	M/s. Karnataka Village and Agro Industries, Sy. No. 274/1, No. 371/5, West NH-4-PB Road, Avaragere,
Applicant	:	Davangere, Karnataka-57700 The Manufacturer

KARNATAKA VILLAGE & AGRO INDUSTRIES KVAI 5TN TIPPINGTRACTOR TRAILER

Report No. : T-83/1379

Month: May

Year: 2022



Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.) T-83/1379

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 12.1 Dimensional requirements of single axle (semitrailer) Conforms to IS 8213:2020.
- 12.2 To protect from mud and soil the rubber flaps are provided at rear end of the wheels.
- 12.3 The lighting arrangement of trailer is not provided as per IS 8213:2020. This should be looked into for corrective action.
- 12.4 The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.5 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.6 The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.7 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.8 The Slow moving emblem & T sign is not provided. This may be provided
- 12.9 An axle assemble is not designed by its class and wheel track. This should be looked into corrective action.

T-83/13	379	KARNATAKA VILLAGE & A KVAI 5TN TIPPING TRA		COMMERCIAL (ICT)
12.10	Serv forr shal as pers	equacy of literature: vice manual parts catalogs of tra n which is not adequate. Howev Il be brought out in Hindi and o ber IS 8132: 1999 (Reaffirmed sonnel.	ver, operation manual a ther regional language	nd parts catalogues in booklet forn
	1	<u>ESTING AUTHORITY:</u>		1
D.C. MOULI AGRICULTURAL ENGINEER			Clars	
P.KAMALABAI SENIOR AGRICULTURAL ENGINEER			P. b. he	-
K.K. NAGLE DIRECTOR			Orenge	

13. Applicant comments

We have noted the suggestions; we will make all possible necessary changes in future