

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्याNo: T-107/1444
माह Month: November, 2022
Validity : 31.10.2029



SRI VENKATA SHIVA SAI SVSSA TRAILER 5 TNE



सत्यमेव जयते

भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

SOUTHERN REGION FARM MACHINERY TRAINING AND TESTING INSTITUTE

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele.: 08551-286441

T-107/1444	SRI VENKATA SHIVA SAI SVSSA TRAILER 5 TNE	COMMERCIAL (ICT)
-------------------	--	-----------------------------

Manufacturer : M/S SRI VENKATA SHIVA SAI AGRO INDUSTRIES
PODHILI ROAD, DARSIPRAKASAM DIST., A.P.,
INDIA- 523247

Applicant : The Manufacturer

SRI VENKATA SHIVA SAI SVSSA TRAILER 5 TNE

Report No. : **T-107/1444**

Month: **NOVEMBER**

Year: **2022**



सत्यमेव जयते

Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

2	
3	
4	
5	
6	

- This should be looked into for corrective action.
- 12.2 The specification for trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.3 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.4 The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.5 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.6 An axle assemble is not designed by its class and wheel track. This should be looked into corrective action.

12.8 Adequacy of literature:



Operator's manual, service manual and parts catalogue of trailer were not provided. However, this must be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY

D.C.MOULI AGRICULTURAL ENGINEER	
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)	

13. APPLICANT'S COMMENTS

Sr No.	Our Ref. No.	Applicants comments
1	12.2	We have noted your comments , we will look in to in future products