


व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्याNo: T-129/1514
माहMonth: June, 2023
Validity: 31.05.2030

THIS TEST REPORT IS VALID UPTO 31.05.2030



TRACTOR TRAILER

SRI SRINIVASA AUTO ENGINEERING WORKS SSAEW 05 TON



सत्यमेव जयते

भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

T-129/1514	TRACTOR TRAILER, SRI SRINIVASA AUTO ENGINEERING WORKS SSAEW 05 TON	COMMERCIAL (ICT)
	THIS TEST REPORT IS VALID UPTO 31.05.2030	

Manufacturer : M/s. Sri Srinivasa Auto Engineering Works,
Industrial Estate, Flot No. C-2 & C-3,
Gudiwada-521301, Krishna DT, AP

Applicant : The Manufacturer

TRACTOR TRAILER
SRI SRINIVASA AUTO ENGINEERING WORKS SSAEW 05 TON

Report No. : T-129/1514 Month : June Year: 2023



Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

T-129/1514	TRACTOR TRAILER, SRI SRINIVASA AUTO ENGINEERING WORKS SSAEW 05 TON		COMMER (ICT)
	THIS TEST REPORT IS VALID UPTO 31.05.2030		
		, month & year of manufacturer , serial number , size , required size of prime mover (kW), weight (Kg)	

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION



- 12.1 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.2 The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.3 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.4 The "Slow Moving Vehicle Emblem" & T signs are not provided. These are to be provided.
- 12.5 An axle assembly is not designed by its class and wheel track. This should be looked into corrective action.

T-129/1514	TRACTOR TRAILER, SRI SRINIVASA AUTO ENGINEERING WORKS SSAEW 05 TON	COMMERCIAL (ICT)
	THIS TEST REPORT IS VALID UPTO 31.05.2030	

12.10 Adequacy of literature:

Service manual parts catalogues of trailer were not provided. Operation manual and parts catalogue should be brought out in Hindi and regional languages as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D.C. MOULI AGRICULTURAL ENGINEER	
P.KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)	

13. Applicant Comments

We have noted your comments and recommendations we will do the necessary action on next production lot.