व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: Machine-347/1163 माह/Month: May, 2020 Validity: 30.04.2025



MHASWADKAR BAM 135 POWER WEEDER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare
कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare
दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele./FAX: 08551-286441

Machine- 347/1163

MHASWADKAR BAM 135 POWER WEEDER

COMMERCIAL (ICT)

Manufacturer : M/s. Chongqing Dinking Power

Machinery Co. Ltd., Caojie

Development Area, Industrial Park,

Hechuan, Chongqing China.

Applicant : M/s. Mhaswadkar Autolines Pvt. Ltd.,

283/3/1B, Karanje, New Radhika

Road, Near Market Yard,

Satara-415001, Maharashtra, India.

MHASWADKAR BAM 135 POWER WEEDER

Report No.: Machine-347/1163 Month: May Year: 2020



Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

Page 2 of 32

Machine- 347/1163

MHASWADKAR BAM 135 POWER WEEDER

COMMERCIAL (ICT)

17. COMMENTS & RECOMMENDATIONS

17.1 Engine Performance:

- 17.1.1 The maximum power and rated power were observed as 5.4 & 4.5 kW under natural ambient condition against the declared value of 5.2 & 5.1 kW respectively.
- 17.1.2 Specific fuel consumption of engine corresponding to maximum power was recorded as 198 g/kWh against the declared value of 295 g/kWh. This should be looked into for corrective action
- 17.1.3 Max. Torque was observed as 20.86 Nm against the declared value of 16.5 Nm.
- 17.1.4 Back up torque of engine was observed as 7.25 %, against the declared value of 11 %. This should be looked into for corrective action.
- 17.1.5 During varying speed test of engine at both natural & high ambient conditions after attaining max. torque at 20.86 Nm & 20.16 Nm respectively, while further loading, sudden drop of engine speed and thick black smoke was noticed.
- Max. Noise at operator's ear level was observed as 95 dB (A), which is higher than the limit specified by the ILO. Therefore, this should be looked into for corrective action
- 17.3 The amplitude of mechanical vibration on most of the assemblies of the Power Weeder was observed up to the maximum extent of 502 microns, Which is directly concerned with Operator's Health, Safety and Comfort. Besides, it also adversely affect the useful life of the components. In view of the above, this should be taken care for corrective action.
- 17.4 The hardness of rotary blades do not conform to the requirement of IS 6690:1981 (Reaffirmed 2012). This should be looked into for corrective action.
- 17.5 Silicon content of the chemical composition of rotary blade is not as per the requirement of IS 6690:1981. This should be looked into for corrective action.

Machine-347/1163

MHASWADKAR BAM 135 POWER WEEDER

COMMERCIA (ICT)

17.6 The provided labeling plate should be as per the requirement IS.

17.7 Technical literature:

Operation manual and parts catalogue of power weeder and in separation booklets were supplied with the test sample for reference during the test is however, recommended that same may be revised and bought out Hindi & other regional languages as per IS 8132:1999 (Reaffirmed 2004 for the sake of user & technical personnel.

TESTING AUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER	B
Dr. P.P. RAO DIRECTOR	P-P. Ras

18. APPLICANT'S COMMENTS

Para No.	Our reference	Applicant's comments	
18.1	17.1	We have noted the comments and will inform to our	
		manufacturer to take care of it	
18.2	17.2	We will look into it regarding this matter	
18.3	17.3	We will look into for reducing the mechanical vibration	
	esta comme	in future products	
18.4	17.4 & 17.5	We will make possible necessary changes in rotary blade	
18.5	17.6	Point is noted and will try to implement for further	
18.6	17.7	We will brought out the literature as per your	
		recommendation	