व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: T-62/1189 माह/Month: August, 2020 Validity: 31.07.2027



HINDUSTAN AGRICULTURAL IMPLEMENTS HAI-5 TT FIVE TONNE TIPPING TRACTOR TRAILER



भारत सरकार Government of India कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि, सहकारिता एवं किसान कल्याण विभाग Department of Agriculture, Cooperation and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने – 515 731, जिला: अनंतपुर (आं. प्र.) Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: <u>fmti-sr@nic.in</u>

Tele./FAX: 08551-286441

Manufacturer : M/s. Hindustan Agricultural Implements, Pangal Road, S.V. Puram (P), Anantapur Dist - 515 003, Andhra Pradesh, **India**.

Applicant

: The Manufacturer

HINDUSTAN AGRICULTURAL IMPLEMENTS HAI-5 TT Five Tonne Tipping Tractor Trailer

Report No. : T-62/1189

Month: August

Year: 2020



Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441 Website: <u>http://srfmtti.dacnet.nic.in/</u> Fax: 08551-286441 E-mail: <u>fmti-sr@nic.in</u>

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

11. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 11.1 Dimensional requirements of single axle (semitrailer) conforms to IS 8213:2000.
- 11.2 To protect from mud and soil the rubber flaps are not provided at rear end of the wheels.
- 11.3 The lightening arrangement of trailer is not provided as per IS 8213:2000. This should be looked into for corrective action.
- 11.4 The specification of trailer does not conform in full, to the IS 8213:2000. This should be looked into for corrective action.
- 11.5 The dimensions of hydraulic tipping cylinder does not meet, in full to the requirement of IS 12371:1988. This should be taken care for corrective action
- 11.6 The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 1999). This should be taken care for corrective action.
- 11.7 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 11.8 The provided labeling plate should be as per the requirement of IS.

T-
62/1189HINDUSTAN AGRICULTUAL IMPLEMENTS HAI-
5 TT FIVE TONNE TIPPING TRACTOR TRAILERCOMMERCIAL
(ICT)

11.9 Adequacy of literature:

Operation manual, maintenance manual cum parts catalogue of trailer in English was provided in single booklet form for reference during the test. However, this may be brought out in Hindi and other regional languages as per IS 8132: 1999 (Reaffirmed 2004) for the sake of user & technical personnel.

TESTING AUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER	BI
Dr. P.P. RAO DIRECTOR	P.P. Rac

12. APPLICANT'S COMMENTS

"We will consider all your suggestions during the next production level".