व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्याधNo: T-81/1377 माहधMonth: May, 2022 Validity: 30.04.2029



SHIV AGRO INDUSTRIES SHIV 5 THE TIPPING TRACTOR TRAILER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele.: 08551-286441

Page 1 of 30

T-81/1377

SHIV AGRO INDUSTRIES SHIV 5 TNE TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/s. SHIV AGRO INDUSTRIES, Goregaon Road,

Near Govt. I.T.I., Gondia-441601, Maharashtra,

India.

Applicant : The Manufacturer

SHIV AGRO INDUSTRIES SHIV 5 TNE TRACTOR TRAILER

Report No.: **T-81/1377** Month: May Year: 2022



Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/ E-mail: fmti-sr@nic.in

T-81/1377

SHIV AGRO INDUSTRIES SHIV 5 TNE TRACTOR TRAILER

COMMERCIAL (ICT)

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 12.1 Dimensional requirements of single axle (semitrailer) Conforms to IS 8213:2020.
- To protect from mud and soil the rubber flaps are provided at rear end of the wheels.
- 12.3 The lighting arrangement of trailer is not provided as per IS 8213:2020. This should be looked into for corrective action.
- The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.5 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.7 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.8 The Slow moving emblem & T sign is not provided. This may be provided
- 12.9 An axle assemble is not designed by its class and wheel track. This should be looked into corrective action.

T-81/1377

to

he

his

20.

the ive

t of

, in for

ed ould

SHIV AGRO INDUSTRIES SHIV 5 TNE TRACTOR TRAILER

COMMERCIAL (ICT)

12.10 Adequacy of literature:

Service manual parts catalogs of trailer were provided in a printed literature form which is not adequate. However, operation manual and parts catalogue shall be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER	
P.KAMALABAI SENIOR AGRICULTURAL ENGINEER	P. Le Bai
K.K. NAGLE DIRECTOR	They !

13. Applicant Comments

Para No.	Our Ref. No.	Applicants comments
13.1	12.3 to 12.9	We will correct it as per the IS
13.2	12.10	We will provide the literature as per IS 8132: 1999

of 30