व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्याधNo:T-88/1387 माहधMonth: June, 2022 Validity: 31.05.2029



PERFECT AGRO ENTERPRISES PAE 5 TON TRACTOR TRAILER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिलाः अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele.: 08551-286441

T-88/1387

PERFECT AGRO ENTERPRISES PAE 5 TON TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/S. PERFECT AGRO ENTERPRISES, 1, Gondawale,

Dahiwadi, District: - SATARA, MAHARASHTRA-

415540, India

Applicant : The Manufacturer

PERFECT AGRO ENTERPRISES PAE 5 TON TRACTOR TRAILER

Report No.: **T-88/1387** Month: **June** Year: **2022**



Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/
E-mail: fmti-sr@nic.in

T-88/1387

PERFECT AGRO ENTERPRISES PAE 5 TON TRACTOR TRAILER

COMMERCIAL (ICT)

12. COMMENTS AND RECOMMENDATION

- 12.1 Dimensional requirements of single axle (semitrailer) conform to IS 8213:2020.
- 12.2 To protect from mud and soil the rubber flaps are not provided at rear end of the wheels.
- The lighting arrangement of trailer is not provided as per IS 8213:2020. This should be looked into for corrective action.
- 12.4 The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2020. This should be looked into for corrective action.
- 12.7 The provided slow moving emblem at rear side of trailer should be as per IS
- 12.8 An axle assemble is not designated by its class and wheel track This should be looked into for corrective action.

T-88/1387

to

of

his

20.

the

tive

i, in

for

IS

ould

PERFECT AGRO ENTERPRISES PAE 5 TON TRACTOR TRAILER

COMMERCIAL (ICT)

12.8 Adequacy of literature:

Operators manual, service manual and parts catalogue of trailer ware not provided in single booklet form for reference during the test. However, this may be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D.C .MOULI AGRICULTURAL ENGINEER	187 818
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER	P. W. Ba.
K.K. NAGLE DIRECTOR	Day

13. Applicants Comments

Para No.	Our Ref. No.	Applicants comments
13,1	12.2	We have noted the suggestion, we will take corrective necessary action in
		future products
13.2	12.3	We will search for the possibilities to meet the requirement of IS
13.3	12.4	We will take corrective in future production level
13.4	12.5	We will inform to our principle supplier to match the IS requirement
13.5	12.6	We will work on in future products to match the requirement of IS 8213
13.6	12.7	This should be looked into for corrective action
13.7	12.8	We will work on it for our future products
13.8	12.9	We will make the necessary changes in literature

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

Page 30 of 30

of 30