

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्याNo: T-97/1401
माहMonth: July, 2022
Validity : 30.06.2029



**SHRI KRISHNA TRAILERS AND ENGINEERING WORKSHOP SKTE 5TT
TRACTOR TRAILER**



सत्यमेव जयते

भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele.: 08551-286441

T-97/1401	SHRI KRISHNA TRAILERS AND ENGINEERING WORKSHOP SKTE 5TT TRACTOR TRAILER	COMMERCIAL (ICT)
------------------	--	-----------------------------

Manufacturer : M/S. Shri Krishna Trailers and Engineering
Workshop, Sy. No. 109/2A, Nanded Road, Basmath,
District :- HINGOLI, MAHARASHTRA-431512, India

Applicant : The Manufacturer

**SHRI KRISHNA TRAILERS AND ENGINEERING WORKSHOP SKTE 5TT
TRACTOR TRAILER**

Report No. : T-97/1401

Month: July

Year: 2022



सत्यमेव जयते

Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

T-97/1401	SHRI KRISHNA TRAILERS AND ENGINEERING WORKSHOP SKTE 5TT TRACTOR TRAILER	COMMERCIAL (ICT)
-----------	--	---------------------




12. COMMENTS AND RECOMMENDATION

- 12.1 Dimensional requirements of single axle (semitrailer) conform to IS 8213:2020.
- 12.2 To protect from mud and soil the rubber flaps are not provided at rear end of the wheels.
- 12.3 The lighting arrangement of trailer is not provided as per IS 8213:2020. This should be looked into for corrective action.
- 12.4 The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.5 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.6 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2020. This should be looked into for corrective action.
- 12.7 The provided slow moving emblem at rear side of trailer should be as per IS
- 12.8 An axle assemble is not designated by its class and wheel track This should be looked into for corrective action.

**12.8 Adequacy of literature:**

Operator's manual, service manual and parts catalogue of trailer were not provided. However, this must be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D C MOULI AGRICULTURAL ENGINEER	
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER	
K.K. NAGLE DIRECTOR	

13. Applicants Comments

No Commets