

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्याNo: T-108/1445
माहMonth: November, 2022
Validity : 31.10.2029



CHOPADE WELDING WORKS CWW DHANANJAY 5TON TRAILER



सत्यमेव जयते

भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garlandinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele.: 08551-286441

T-108/1445	CHOPADE WELDING WORKS CWW DHANANJAY 5TON TRAILER	COMMERCIAL (ICT)
-------------------	---	-----------------------------

Manufacturer : M/S Chopade welding Works, Property No. 1616, Main road,
Undri, Chikhli, Bhuldana-444303, Maharashtra , India.

Applicant : The Manufacturer

CHOPADE WELDING WORKS CWW DHANANJAY 5TON TRAILER

Report No. : **T-108/1445**

Month: **NOVEMBER**

Year: **2022**



सत्यमेव जयते

Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in



T-108/1445	CHOPADE WELDING WORKS CWW DHANANJAY5TON TRAILER	COMMERCIAL (ICT)
------------	--	---------------------

- 12.4 The dimensions of ring type hitch does not meet, in full, the requirement of IS T1370:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.5 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.6 An axle assemble is not designed by its class and wheel track. This should be looked into corrective action.

12.8 Adequacy of literature:

Operator's manual, service manual and parts catalogue of trailer were not provided. However, this must be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D.C. MOULI AGRICULTURAL ENGINEER	
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)	

13. Applicants comments

We have gone through the test report, we have noted your comments recommendations, we work on it to implement your suggestions in our future production level