व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्याधNo: T-126/1494

माहधMonth: April, 2023

Validity: 31.03.2030

TEST REPORT IS VALID UPTO 31.03.2030



NEW SHAM INDUSTRIES NSI-3 TOT TIPPING TRACTOR TRAILER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele. 08551-286441

Γ-126/1494

NEW SHAM INDUSTRIES NSI-3 TOT TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer

: M/s. NEW SHAM INDUSTRIES

16/27, Opp. Kolhapur Steels Ltd., Nagaon Road, Pulachi Shiroli, Tal. Hatkanangale, Dist Kolhapur-416122,

Maharashtra, India

Applicant

: The Manufacturer

NEW SHAM INDUSTRIES NSI-3 TOT TIPPING TRACTOR TRAILER

eport No.: T-126/1494

Month: April

Year: 2023





Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare

Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

ebsite: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

Page 2 of 29

T-126/1494 •	NEW SHAM INDUSTRIES NSI-3 TOT TIPPING TRACTOR TRAILER
--------------	--

COMMERCIAI (ICT)

- 12.5 The dimensions of ring type hitch does not meet, in full, the requirement IS 11270:1980 (Reaffirmed 2019). This should be taken care for correctivaction.
- The dimensions of various components of axle assembly do not conform, full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- 12.7 The Slow moving emblem & T sign are not provided. This may be provided
- An axle assembly is not designated by its class and wheel track. This shou be looked into corrective action.

12.10 Adequacy of literature:

Service manual parts catalougs of trailer were provided in a printed literature form which is not adequate. However, operation manual and parts catalog shall be brought out in Hindi and other regional languages in **booklet for** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technic personnel.

TESTING AUTHORITY:

D.C. MOULI AGRICULTURAL ENGINEER

P.KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)

P. K. Ba.

13. Applicant Comments

We will gone through your comments and recommendation changes will happens of future lot.