व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (ICT) संख्या/No: T-136/1534 माह/Month: August, 2023 Validity: 31.07.2030

THIS TEST REPORT IS VALID UPTO 31.07.2030



TRACTOR TRAILER PSW ADITYA-HTT5T



भारत सरकार Government of India

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लिदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.) Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele. 08551-286441

T-136/1534

TRACTOR TRAILER

PSW ADITYA-HTT5T

THIS TEST REPORT IS VALID UPTO 31.07.2030

COMMERCIAL (ICT)

Manufacturer

: M/s. Pawar Steel Works,

Plot. No. C-2, MIDC Area,

Jafrabad, Jalna - Dist,

Maharastra-431206.

Applicant

: The Manufacturer

TRACTOR TRAILER

PSW ADITYA-HTT5T

Report No.: T-136/1534

Month: August

Year: 2023



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

Page 2 of 28

T-136/1534	TRACTOR TRAILER PSW ADITYA-HTT5T THIS TEST REPORT IS VALID UPTO 31.07.2030	COMMERCIAL (ICT)
	address of manufacturer, country of origin, make, model , month & year of manufacturer, serial number, size, required size of prime mover (kW), weight (Kg)	

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 12.1 The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.3 The dimensions of ring type hitch does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.

12.7 Adequacy of literature:

Service manual and parts catalogues of trailer were not provided. However, operation manual and parts catalogue should be brought out in Hindi and regional languages as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D.C. MOULI
AGRICULTURAL ENGINEER

Dr. B.M. NANDEDE
DIRECTOR

DIRECTOR

13. APPLICANT'S COMMENTS

We have gone through all your comments & we will inform our manufacturing unit about your comment and recommendation.

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTI-ANANTAPUR, (A.P.)

123gq 28 of 28