# व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: T-47/1116 माह/Month: January, 2020

Validity: 31.12.2026



# BT ENGINEERING WORKS BT 5 TT FIVE TONNE TRACTOR TRAILER



#### भारत सरकार

#### **Government of India**

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतप्र (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele./FAX: 08551-28644

T-47/1116

# BT ENGINEERING WORKS BT 5 TT FIVE TONNE TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/s. BT Engineering Works,

SJM College, Holalkere Road, Near Kanive, Chitradurga - 577 501, Karnataka, **INDIA**.

Applicant : The Manufacturer

#### BT ENGINEERING WORKS BT 5 TT FIVE TONNE TRACTOR TRAILER

Report No.: T-47/1116 Month: January Year: 2020



#### **Government of India**

Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441 Fax: 08551-286441 Website: http://srfmtti.dacnet.nic.in/ E-mail: fmti-sr@nic.in

T-47/1116

# BT ENGINEERING WORKS BT 5 TT FIVE TONNE TRACTOR TRAILER

COMMERCIAL (ICT)

### 11. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 11.1 To protect from mud and soil the rubber flaps are provided at rear end of the wheels.
- Dimensional requirements of single axle (semitrailer) conforms to IS 8213:2000.
- The lightening arrangement of trailer is not provided as per IS 8213:2000. This should be looked into for corrective action.
- The specification of trailer does not conform in full, to the IS 8213:2000. This should be looked into for corrective action.
- The dimensions of hydraulic tipping cylinder does not meet, in full to the requirement of IS 12371:1988. This should be taken care for corrective action
- The dimensions of ring does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 1999). This should be taken care for corrective action.
- 11.7 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be looked into for corrective action.
- The provided labeling plate should be as per the requirement of IS.

T-47/1116

# BT ENGINEERING WORKS BT 5 TT FIVE TONNE TRACTOR TRAILER

COMMERCIA (ICT)

### 11.9 Adequacy of literature:

Operation manual, Service manual, maintenance manual and parts catalog of trailer in English was provided in single booklet form for reference during the test. However, this may be brought out in Hindi and other region languages as per IS 8132: 1999 (Reaffirmed 2004) for the sake of user technical personnel.

### **TESTING AUTHORITY:**

B.N. DIXIT AGRICULTURAL ENGINEER	BI
Dr. P.P. RAO DIRECTOR	P.P. Rag

#### 12. APPLICANT'S COMMENTS

All your comments and suggestions are highly helpful for us to improve of product in future.