

व्यावसायिक परीक्षण रिपोर्ट
COMMERCIAL TEST REPORT
(FIRST BATCH TEST)

संख्या / No.: Machine-477/1480

माह: / Month: February, 2023 THIS
TEST REPORT IS VALID UPTO 31/01/2028



POWER REAPER KAMCO KR-120B



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTION]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele./FAX: 08551-286441

Machine- 477/1480	POWER REAPER KAMCO KR-120B	COMMERCIAL (FIRST BATCH TEST)
	THIS TEST REPORT IS VALID UPTO 31/01/2028	

Manufacturer : M/s. Kerala Agro Machinery Corporation Ltd., Athani P.O., Ernakulam, Kerala-683 585.

Applicant : The Manufacturer

POWER REAPER KAMCO KR-120B

Report No. : **Machine-477/1480**

Month: February

Year: 2023



**Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTION]**



Telephone No. 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Machine- 477/1480	POWER REAPER KAMCO KR-120B		COMMERCIAL (FIRST BATCH TEST)
	THIS TEST REPORT IS VALID UPTO 31/01/2028		
18.4	Adequacy of literature:	: Operation manual, Part catalogue and Workshop/service manual of power reaper Engine	Operator's manual, technical manual and parts catalogue of power reaper

TESTING AUTHORITY:

D.C. MOULI AGRICULTURAL ENGINEER	
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)	

19. APPLICANT'S COMMENTS

S No.	Our reference	Applicant's comments
1	17.5	Action will be taken to control the vibration within the specified limit by providing suitable anti vibration pads in the engine foundation
2	17.8	Action will be taken to correct the chemical composition as per the IS 6025 : 1982
3	17.10	Action will be taken to revise the instruction manual/service book/parts catalogue as per IS 8132:1999