Th-37/1033

KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)

COMMERICAL (ICT)

माह / Month: July, 2019

`व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)

संख्या / No: Th-37/1033

COMMERCIAL TEST REPORT

(INITIAL)



KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)



भारत सरकार

Government of India

कृषिएवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Th-37/1033

KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)

COMMERICAL (ICT)

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele./FAX: 08551-286441

Manufacturer : M/s. Kumar Industries,86,Karur

Main Road, Naduppalayam,

Erode - 631 154, Tamil Nadu, **India**.

Name of Applicant : The Manufacturer

KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)

Report No.: Th-37/1033 Month: July Year: 2019



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441 Fax: 08551-286441

Th-37/1033		KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)		COMMERICAL (ICT)
9.2	label writted pictor. The typos accordance to seen pictur.	In thresher shall be fitted with a language containing cautionary notices the invernacular language and their orial representation. In size of the pictures and the graphy of the letters shall be selected right to the size of the label or poster the distance at which these have to be or read. The minimum size for the shall be 40 mm. The colour of symbols should be the for "pictorial representation" and for "Not to Do": (Annex-B)	Provided	Conforms

9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of Multi crop thresher.

10. DEFECTS, BREAKDOWNS AND REPAIRS

No defect/breakdown was occurred during entire period of field & lab tests.

11. COMMENTS & RECOMMENDATIONS

- 11.1 The material of construction of different components of thresher is conforming as per IS 6284 : 1985
- Provision for different adjustments on thresher is provided as per IS 6284:1985.
- 11.3 Most of the parameters are meeting the requirement of IS 9020:2002.
- The specification of feeding chute does not conform to IS: 9020-2002 (Reaffirmed 2012). This should be looked into.
- 11.5 Standard PIC & its yoke bore for 6-splined conforming to IS 4931 : 1995 should be provided.
- 11.6 The labeling plate should be provided as per the requirements of IS.

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR (A.P.)	Page 33 of 38
--	---------------

Th-37/1033

KUMAR KTM - 1 MULTI CROP THRESHER (TRACTOR PTO OPERATED)

COMMERICAL (ICT)

11.7 Adequacy of literature supplied with the machine:

Operation, Service, Maintenance manual cum part catalogue of thresher in English was provided in brief in a single booklet form for reference during the test. However, this may be brought out in Hindi and other regional languages as per IS 8132:1999 (Reaffirmed 2004) for the sake of user & technical personnel.

TESTINGAUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER	B
Dr. P.P. RAO DIRECTOR	1-1. Las

12. APPLICANT'S COMMENTS

"As per your suggestions we will take all corrective actions in our future production".