व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No:T-34/1065 माह/Month: September, 2019

Validity: 31.08.2026



SRI MANJU INDUSTRIES SMI-5 TON FIVE TONNE TIPPING TRACTOR TRAILER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele./FAX: 08551-286441

T-34/1065

SRI MANJU INDUSTRIES SMI-5 TON FIVE TONNE TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/s. Sri Manju Industries,

By Pass Road, Paramathi Velur Taluk,

Namakkal District - 638182,

Tamil Nadu, India

Applicant : The Manufacturer

SRI MANJU INDUSTRIES SMI-5 TON FIVE TONNE TIPPING TRACTOR TRAILER

Report No.: T-34/1065 Month: September Year: 2019



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/

Fax: 08551-286441

E-mail: fmti-sr@nic.in

T-34/1065

SRI MANJU INDUSTRIES SMI-5 TON FIVE TONNE TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

8. LOAD MAINTENANCE TEST (Trailer bucket in fully raised position)

Date of test : 23.07.2019

Operating conditions : Trailer parked on level ground

Hydraulic oil temperature before start

of test, °(C)

Initial height from ground level, (mm) : 3350

Elapsed time (Min.)		Cumulative drop in height of unloading box, (mm)
5	:	2
10	:	3
15	:	3
20	:	4
25	:	6
30	:	7
Leakage of hydraulic fluid from	:	None
any part of hydraulic system		
Working of hydraulic system	:	Satisfactory

9. EASE OF OPERATION & ADJUSTMENTS

No difficulty was observed during the operation and adjustment of Trailer.

10. DEFECTS, BREAKDOWNS AND REPAIRS

No defect/breakdown and repair was occurred during entire period of testing.

11. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 11.1 To protect from mud and soil the rubber flaps are provided at rear end of the wheels.
- Dimensional requirements of single axle (semitrailer) conform to IS 8213:2000.
- Lighting arrangement of trailer is not provided as per IS 8213:2000. This should be locked into for corrective action.
- The specification of trailer does not conform in full, to the IS 8213:2000. This should be looked into for corrective action.

T-34/1065

SRI MANJU INDUSTRIES SMI-5 TON FIVE TONNE TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

- The provided hitch on the trailer is rotatable, but it should provided with a spring for shock absorption. fixed type.
- The dimensions of hydraulic tipping cylinder does not meet, in full to the requirement of IS 12371:1988. This should be taken into for corrective action
- The dimensions of ring does not meet, in full, the requirement of IS 11270:1980 (Reaffirmed 1999). This should be taken into for corrective action.
- The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2000. This should be taken into for corrective action.
- 11.9 Labeling plate should be provided as per the requirement of IS.

11.10 Adequacy of literature:

Operation manual, Service manual, and parts catalogue of trailer in English was provided in single booklet form for reference during the test. However, this may be brought out in Hindi and other regional languages as per IS 8132: 1999 (Reaffirmed 2004) for the sake of user & technical personnel.

TESTING AUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER	
Dr. P.P. RAO DIRECTOR	P. Rao

12. APPLICANT COMMENTS

"All the suggestions are noted. And we will make all possible necessary changes in future production".

