व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: T-54/1142 माह/Month: April, 2020 Validity: 31.03.2027



S.R.TRADERS SRT 5 TON TIPPING TRACTOR TRAILER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare
कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare
दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute
ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: <u>fmti-sr@nic.in</u> Tele./FAX: 08551-286441

T-54/1142

S.R.TRADERS SRT 5 TON TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/s. S.R. Traders,

140/113, M.D. Complex, 3rd Ward,

Chamraj Nagar Road,

Gundalpet-571 111, Karnataka, India.

Applicant : The Manufacturer

S.R.TRADERS SRT 5 TON TIPPING TRACTOR TRAILER

Report No.: T-54/1142 Month: April Year: 2020



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441 Fax: 08551-286441

T-54/1142

S.R.TRADERS SRT 5 TON TIPPING TRACTOR TRAILER

COMMERCIAL (ICT)

8. LOAD MAINTENANCE TEST (Trailer bucket in fully raised position)

61

Date of test : 28.02.2020

Operating conditions : Trailer parked on level ground

Hydraulic oil temperature before start :

of test, °(C)

Initial height from ground level, (mm) : 3400

Elapsed time (Min.)		Cumulative drop in height of unloading box, (mm)
5	:	5
10	:	8
15	:	11
20	:	13
25	:	16
30	:	18
Leakage of hydraulic fluid from	:	None
any part of hydraulic system		
Working of hydraulic system	:	Satisfactory

9. EASE OF OPERATION & ADJUSTMENTS

No difficulty was observed during the operation and adjustment of Trailer.

10. DEFECTS, BREAKDOWNS AND REPAIRS

No defect/breakdown and repair was occurred during entire period of testing.

11. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- The provided hitch on the trailer is rotatable type and provided with a shock absorbing arrangement.
- To protect from mud and soil the rubber flaps are provided at rear end of the wheels.
- Dimensional requirements of single axle (semitrailer) conforms to IS 8213:2000.
- Lighting arrangement is not provided as per IS 8213:2000. This should be locked into for corrective action.

T-54/1142

S.R.TRADERS SRT 5 TON TIPPING TRACTOR TRAILER

COMMERCIA (ICT)

- The specification of trailer does not conform in full, to the IS 8213:20 This should be looked into for corrective action.
- 11.6 The dimensions of hydraulic tipping cylinder does not meet, in full to requirement of IS 12371:1988. This should be taken into for correct action.
- 11.7 The dimensions of ring type hitch does not meet, in full, the requirement IS 11270:1980 (Reaffirmed 1999). This should be taken into for correct action.
- 11.8 The dimensions of various components of axle assembly do not conform full, the requirement of IS 8213:2000. This should be taken into corrective action.
- 11.9 Provided labeling plate should be as per the requirement of IS.

11.10 Adequacy of literature:

Operation manual, Service manual, and parts catalogue of trailer in Eng was provided in single booklet form for reference during the test. However, this may be brought out in Hindi and other regional languages as IS 8132: 1999 (Reaffirmed 2004) for the sake of user & technical personn

TESTING AUTHORITY:

B.N. DIXIT AGRICULTURAL ENGINEER 00

Dr. P.P. RAO DIRECTOR P-P-Ras

12. APPLICANT'S COMMENTS

"In future we will follow your suggestions while manufacturing the trailer",

as (i)