

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्याNo: Machine-440/1408
माहMonth: August, 2022
Validity: 31.07.2027



Really RAPL-PCHB-52S BRUSH CUTTER



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele: 08551-286441

Machine-440/1408	Really RAPL-PCHB-52S BRUSH CUTTER	COMMERCIAL (ICT)
-------------------------	--	-------------------------

Manufacturer : **M/s. Taizhou Dongfeng Technology CO., LTD. No. 289, Houcang Rd., Zeguo town, Wenling city, Zhejiang province, China 317500**

Name of Applicant : **M/s. REALLY AGRITECH Pvt. Ltd., NO. G/5 Gala NO. 3, 4 Gr Floor, Bhumi World Industrial Park NH/3 Pimpalas Bhivandi, Bhivandi, Thane, Maharashtra, 421302,India.**

Really RAPL-PCHB-52S BRUSH CUTTER

Report No.: **Machine-440/1408**

Month: **August**

Year: **2022**



Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

**SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE,
ANANTAPUR, (A.P.)**


Page 2 of 24




Machine-440/1408	Really RAPL-PCHB-52S BRUSH CUTTER	COMMERCIAL (ICT)
------------------	-----------------------------------	------------------

- 16.6 The chemical composition of square blade & circular disc was not as per requirement of the relevant code IS 6025:1982 (Reaffirmed 1999) & therefore it should be looked into for the corrective action.
- 16.7 The provided labeling plate should be as per the requirement of the IS. The Engine serial number should be given with embossing on engine body instead of sticker during production.
- 16.8 **Adequacy of literature supplied with the machine:**
Operators instruction book cum parts catalogue of brush cutter was not supplied with the brush cutter for reference during the test. It is recommended that to brought out as per IS: 8132- 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY


D.C. MOULI
AGRICULTURAL ENGINEER


P. KAMALABAI
SENIOR AGRICULTURAL ENGINEER


K.K. NAGLE
DIRECTOR

17. Applicants Comments

We will intimate our manufacturer to take the necessary action to implement the recommendation for future production. We will take the necessary action which can be executed from our side.

ANNEXURE- I