

व्यावसायिक परीक्षण रिपोर्ट

COMMERCIAL TEST REPORT  
(First Batch test)

संख्या / No.: Machine- 441/1409

माह: / Month: August, 2022

Validity: 31.07.2027



**YANMAR YR60D 6 ROW RIDING TYPE  
RICE TRANSPLANTER**



सत्यमेव जयते

भारत सरकार

**Government of India**

कृषि एवं किसान कल्याण मंत्रालय

**Ministry of Agriculture and Farmers Welfare**

कृषि एवं किसान कल्याण विभाग

**Department of Agriculture and Farmers Welfare**

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

**Southern Region Farm Machinery Training and Testing Institute**

ट्रैक्टर नगर, गार्लदिन्ने -731 515, जिला (.प्र.आं) अनंतपुर :

**Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)**

**[An ISO 9001:2015 CERTIFIED INSTITUTION]**

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: [fmti-sr@nic.in](mailto:fmti-sr@nic.in)

Tele./FAX: 08551-286441

<b>Machine- 441/1409</b>	<b>YANMAR YR60D 6 ROW RIDING TYPE RICE TRANSPLANTER</b>	<b>COMMERCIAL</b>
------------------------------	---	-------------------

Manufacturer : Yanmar Agricultural Equipment (China)  
Co. Ltd., No. 8 Huangshan Road  
New District, Wuxi,  
Jiangsu Prov., **China.**

Applicant : Yanmar Coromandel Agrisolutions  
Private Limited, No 19, Qausar power 1<sup>st</sup>  
floor, Khaddat Nawaz Khan Road,  
Nungambakkam, chennai-600006

**YANMAR YR60D 6 ROW RIDING TYPE RICE TRANSPLANTER**

Report No.: **Machine- 441/1409**

Month: August

Year: 2022



**Government of India**  
**Ministry of Agriculture and Farmers Welfare**  
**Department of Agriculture and Farmers Welfare**  
**Southern Region Farm Machinery Training and Testing Institute**  
**Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)**  
**[An ISO 9001:2015 CERTIFIED INSTITUTION]**

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: [fmti-sr@nic.in](mailto:fmti-sr@nic.in)



Machine-441/1409	YANMAR YR60D 6 ROW RIDING TYPE RICE TRANSPLANTER	COMMERCIAL (First Batch-Test)
	Maximum amplitude of vibration at, (micron):	
	-Gear shifting lever	: 38 276
	-Steering wheel	: 48 284
	-Steering clutch lever	: 99 227
	-Accelerator lever	: 29 291
3	Maintenance/service problems:	: None of the problems was observed in the previous sample. None of the problems was observed in the present sample.
4	Adequacy of literature:	: Operation manual, Part catalogue and Workshop/service manual of transplanter Engine Operator's manual, Technical manual and Parts catalogue of trans-planter.

**16.5 Technical literature:**

Operator's manual, technical manual and parts catalogue of Rice Transplanter and engine in separate booklet were supplied with the Rice Transplanter for reference during the test. It is however, recommended that same may be revised in Hindi and other regional languages as per IS 8132 : 1999 (Reaffirmed 2004) for the sake of user & technical personnel.

**TESTING AUTHORITY**

**B.N. DIXIT**  
AGRICULTURAL ENGINEER

**P.KAMALABAI**  
SENIOR AGRICULTURAL ENGINEER

**K.K.NAGLE**  
DIRECTOR

**17. Applicant comments**

Will take suitable corrective action