# व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT (First Batch Test)

संख्या / No.: Machine-442/1410 माह: / Month: August, 2022

Validity: 31.07.2027



# YANMAR YR80D 8 ROW RIDING TYPE RICE TRANSPLANTER



भारत सरकार

#### **Government of India**

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लिदिन्ने-731 515, जिला (.प्र .आं) अनंतपुर:

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

IAn ISO 9001:2015 CERTIFIED INSTITUTION

Website: http://srfmtti.dacnet.nic.in/

E-mail: <u>fmti-sr@nic.in</u> Tele./FAX: 08551-286441

**Machine-** 442/1410

## YANMAR YR80D 8 ROW RIDING TYPE RICE TRANSPLANTER

**COMMERCIAL** (First Batch Test)

Manufacturer : Yanmar Agricultural Equipment (China)

Co. Ltd., No. 8 Huangshan Road

New District, Wuxi, Jiangsu Prov., **China.** 

Applicant : Yanmar Coromandel Agrisolutions

Private Limited, No 19, Qauser power 1<sup>st</sup> floor, Khaddat Nawaz Khan Road,

Nungambakkam, chennai-600006

#### YANMAR YR80D 8 ROW RIDING TYPE RICE TRANSPLANTER

Report No.: Machine-442/1410 Month: August Year: 2022



# Government of India Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTION]

Telephone: 08551-286441

Website: <a href="http://srfmtti.dacnet.nic.in/">http://srfmtti.dacnet.nic.in/</a>
E-mail: <a href="mailto:fmti-sr@nic.in">fmti-sr@nic.in</a>

CIAL Test)	Machine- 442/1410	10.1	YANMAR YR80D 8 ROW RIDING TYPE RICE TRANSPLANTER		
	6.2.7	Mechanical vibration:			
aling		Maximum amplitude of vibration at, (micron):		audidan .	a-
ded rubba 0/950x150		-Gear shifting lever	:	39	272
3/930X130		-Steering handle grip	:	41	280
200		-Steering clutch lever	:	83	268
on each sie		-Accelerator lever	:	57	272
33, big 11 3560	16.3	Maintenance/service problems:	•	None of the problems was observed in the previous sample.	None of the problems was observed in the present sample.
2670	16.4	Adequacy of literature:		Operation manual,	Operator's manual,
3850			:	Part catalogue and	Technical manual
			100	Workshop/service	and Parts catalogue
2350				manual of	of trans-planter.
846	R .			transplanter Engine	
	16.5 Technical literature:				
14.8	Operation, maintenance manual and parts catalogue of Rice Transplanter and engine in separate booklet were supplied with the Rice transplanter for				
272	reference during the test. It is however, recommended that same may be				

revised in Hindi and other regional languages as per IS 8132: 1999 (Reaffirmed 2004) for the sake of user & technical personnel.

### **TESTING AUTHORITY**

B.N. DIXIT AGRICULTURAL ENGINEER

50.66

14.9

106

102

384 43

0.67

90

91

of 46

P.KAMALABAI SENIOR AGRICULTURAL ENGINEER

DIRECTOR

18. Applicant Comments Will take suitable corrective action

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE -ANANTAPUR [An ISO 9001:2015 CERTIFIED INSTITUTION]

Page 44 of 46