## व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT

माहधMonth: August, 2022

संख्याधNo: T-101/1416

Validity: 31.07.2029

(INITIAL)



## JAI JADHAO 5 TONNE TRACTOR TRAILER



#### भारत सरकार

#### **Government of India**

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

**Southern Region Farm Machinery Training and Testing Institute** 

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिलाः अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <a href="http://srfmtti.dacnet.nic.in/">http://srfmtti.dacnet.nic.in/</a>

E-mail: fmti-sr@nic.in Tele.: 08551-286441

T-101/1416

#### JAI JADHAO 5 TONNE TRACTOR TRAILER

COMMERCIAL (ICT)

Manufacturer : M/S Jadhao Agro Industries Pvt Ltd, A-38 Midc

Area, By Pass Road, District: - Amravati, Maharashtra-

444605, India

Applicant : The Manufacturer

## JAI JADHAO 5 TONNE TRACTOR TRAILER

Report No.: **T-101/1416** Month: **August** Year: **2022** 



#### **Government of India**

Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <a href="http://srfmtti.dacnet.nic.in/">http://srfmtti.dacnet.nic.in/</a>
E-mail: <a href="mailto:fmti-sr@nic.in">fmti-sr@nic.in</a>

T-101/1416

# JAI JADHAO 5 TONNE TIPPING TRACTOR TRAILER

COMMERCIAI (ICT)

- The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.5 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.6 The dimensions of various components of axle assembly do not conform, in full, the requirement of IS 8213:2020. This should be looked into for corrective action.
- 12.7 Axle assembly is not designated by its class and wheel track This should be looked into for corrective action.

## 12.8 Adequacy of literature:

Operator's manual, service manual and parts catalogue of trailer were no provided. However, this may be brought out in Hindi and other regional languages in **booklet form** as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

### **TESTING AUTHORITY**

AGRICULTURAL ENGINEER

P.KAMALABAI SENIOR AGRICULTURAL ENGINE

K.K.NAGLE DIRECTOR

13. Applicants Comments

No Comments