
व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)





TRISPAN TAG 52 POST HOLE DIGGER (ENGINE POWERED MANUALLY OPERATED)



भारत सरकार

Government of India

कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग

Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लिदिन्ने ' 515 731, जिलाः अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[AN ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: <u>fmti-sr@nic.in</u> Tele./FAX: 08551-286441

Machine- 458/1436

TRISPAN TAG 52 POST HOLE DIGGER (ENGINE POWERED MANUALLY OPERATED)

COMMERCIAL (ICT)

Manufacturer : M/S. Linyi Grepo Garden Machinery Co Ltd.

The West Of Changlin Street Linshu Country,

Linyi City Shandong, China

Name of Applicant : M/S. Trispan Farm Equipments & Engineerings

121, Tarapur, Patenigan, Jagatsinghpur,

Odisha,754133.India

TRISPAN TAG 52 POST HOLE DIGGER

(ENGINE POWERED MANUALLY OPERATED)

Report No.: Machine-458/1436 Month: October Year: 2022



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[AN ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone No. 08551-286441

Website: http://srfmtti.dacnet.nic.in/
E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE - ANANTAPUR [AN ISO 9001:2008 COMPLIANT INSTITUTION]

Page 2 of 22

	achine- 88/1436	TRISPAN TAG 52 POST HOLE DIGGER (ENGINE POWERED MANUALLY OPERATED)	COMMERCIAL (ICT)
	/	against the requirement of 56±3 HRC as per IS: 6090-1981 (Reaffirmed 2012). This should be looked into for necessary corrective action.	
1	6.7	Chemical composition of augur blade, augur tip and removable impact bit were not conforming as per requirement of the relevant code (IS: 6090-1981 (Reaffirmed 2002)) & therefore it should be looked into for the corrective action.	
10	6.8	The safety gadgets as mentioned in Para 4.0, was provided by the applicant during the test.	
10	6.9	Transmission drive safety provision in the Post hole digger is not provided, whereas it is essential from the safety point of view. Therefore, it must be provided in the future product.	
10	5.10	No labeling plate is provided by the applicant however a metallic labeling plate with Engine serial no and make, model of engine should be revited on the machine during production level	
16	6.11 Adequacy of literature supplied with the machine:		
a. WIT	d 87.01	A printed manual containing operation, maintenance, to instructions and spare parts description in English, is papplicant, which is not sufficient and it needs to be dev	rovided by the
	dia Car	8132-1999 and also in some other regional languages for	or sake of users
A. 9. 2	Paul Column	& technical personnel.	
TESTING AUTHORITY			
			4
. 4		B.N. DIXIT P.KAMALAB	
	A CDICU	B.N. DIXIT P.KAMALAB	AI
AGRICULTURAL ENGINEER SENIOR AGRICULTURAL ENGINEER			

K.K.NAGLE DIRECTOR

17. Applicant Comments

We have noted your comments and recommendation we will take corrective action I future products.

Ma 458

SI. No.

10

11

SO