

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)  
COMMERCIAL TEST REPORT  
(INITIAL)

संख्याधNo: Machine-468/1455  
माहरूधMonth: December, 2022  
Validity: 30.11.2027



**BRUSH CUTTER PUBERT P520BG**



सत्यमेव जयते

भारत सरकार

**GOVERNMENT OF INDIA**

कृषि एवं किसान कल्याण मंत्रालय

**MINISTRY OF AGRICULTURE AND FARMERS WELFARE**

कृषि एवं किसान कल्याण विभाग

**DEPARTMENT OF AGRICULTURE AND FARMERS WELFARE**

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

**SOUTHERN REGION FARM MACHINERY TRAINING AND TESTING INSTITUTE**

ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

**TRACTOR NAGAR, GARLADINNE-515 731, DISTRICT: ANANTAPUR (A.P.)**

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: [fmti-sr@nic.in](mailto:fmti-sr@nic.in)

Tele. 08551-286441

<b>Machine-468/1455</b>	<b>BRUSH CUTTER PUBERT P520BG</b>	<b>COMMERCIAL (ICT)</b>
-------------------------	-----------------------------------	-------------------------

Name of Manufacturer : M/S. SHANDONG HUASHENG PESTICIDE  
( AS PER APPLICANT) MACHINERY CO. LTD, NO.1 ZHONGTIAN RD,  
LINYI HIGH AND NEW INSUDTRIAL  
DEVELOPMENT ZONE, LINYI CITY  
SHANDONG CITY. **CHINA**

Name of Applicant : M/S. PUBERT INDIA PVT. LTD.,  
303, MANOMAYA RESIDENCY, NRI LAYOUT,  
DOUBLE KALKERE ROAD,  
RAMAMURTHYNAGAR,  
BANGALORE

**BRUSH CUTTER PUBERT P520BG**

Report No.: **Machine-468/1455**

Month: **December**

Year: **2022**



सत्यमेव जयते

**Government of India**  
**Ministry of Agriculture and Farmers Welfare**  
**Department of Agriculture and Farmers Welfare**  
**Southern Region Farm Machinery Training and Testing Institute**  
**Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)**  
**[An ISO 9001:2015 CERTIFIED INSTITUTE]**

Telephone: 08551-286441

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: [fmnti-sr@nic.in](mailto:fmnti-sr@nic.in)

Machine- 468/1455	BRUSH CUTTER PUBERT P520BG	COMMERCIAL (ICT)
----------------------	----------------------------	---------------------

- 16.4 A fuel on/off knob may be considered for providing in the fuel system of engine.
- 16.5 The hardness of blades do not conform to the requirement of IS 6690:1981 (Reaffirmed: 2017). This should be looked into for corrective action.
- 16.6 The chemical composition of square blade and circular disc were not as per requirement of the relevant code IS 6025:1982 (Reaffirmed: 2019) & therefore it should be looked into for the corrective action.
- 16.7 The provided labeling plate should be as per the requirement of the IS. Engine serial no and make , model of engine should be given with embossing on engine body instead of sticker during production level
- 16.8 **Adequacy of literature supplied with the machine:**  
The User's manual and spare parts list of brush cutter and engine in English were supplied with the brush cutter for reference during the test. It is however, recommended that same may be revised and brought out as per IS: 8132- 1999 (Reaffirmed:2019) for the sake of user & technical personnel.

**TESTING AUTHORITY**



D.C. MOULI AGRICULTURAL ENGINEER	
P. KAMALABAI SENIOR AGRICULTURAL ENGINEER DIRECTOR(I/C)	

**17. Applicants Comments**

Sr. No.	Our Reference no.	Applicant's Comments
1	16.2,16.3,16.4,16.5,16.6 &16.7	We Pubert India Pvt Ltd, will inform the manufacturer to comply all the points raised by srfmtti in columnno 16 incommnets and recommndation