
व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्याधNo: T-132/1517

माहधMonth: June, 2023

Validity: 31.05.2030

THIS TEST REPORT IS VALID UPTO 31.05.2030



TRACTOR TRAILER RASOOL ENGINEERING WORKS REW 5 TNE



भारत सरकार Government of India

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लिदेन्ने - 515 731, जिला: अनंतपुर (आं. प्र.) Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.) [An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

Tele. 08551-286441

Page 1 of 30

T-132/1517

TRACTOR TRAILER RASOOL ENGINEERING WORKS REW 5 TNE

COMMERCIAL (ICT)

Manufacturer

: M/s. Rasool Engineering Works,

D.No.:13-3-152/1,

Chilakaluripet

Road,

Narasaraopet, Guntur Dist., Andhra

Pradesh-

522601, India.

Applicant

: The Manufacturer

TRACTOR TRAILER

RASOOL ENGINEERING WORKS REW 5 TNE

Report No.: T-132/1517

Month: June

Year: 2023



Government of India

Ministry of Agriculture and Farmers Welfare Department of Agriculture and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

Page 2 of 27

32/1517	TRACTOR TRAILER RASOOL ENGINEERING WORKS REW 5 TNE			COMMERCIAL (ICT)
GVM (gross vehicle weight) or RLW (registered laden weight) as certified by the manufacturer		-kgs	6950	Conforms
Number, description, size and ply rating of tyre as declared by the manufacturer		Provided	Provided	Conforms
Overall	length, mm	2000 to 4100 to be checked	4130	Does not conforms
Overall	width, mm	900 (min) to be checked	1900	Conforms
Overall	height, mm	600 (min)	2510	Conforms
Min,	ground ce, (mm)	300	470	Conforms
	g/labeling of	The labeling plate should be riveted on the body of machine having name and address of manufacturer, country of origin, make, model, month & year of manufacturer, serial number, size, required size of prime mover (kW), weight (Kg)	Provided but not sufficien information	110es not

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 12.1 The lighting arrangement of trailer is not provided as per IS 8213:2020. This should be looked into for corrective action.
- The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.3 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective

full, the requirement of IS 8213:2000. This should be looked into for The Slow Moving Vehicle Emblem and T-signs are not provided. These are 12.6 An axle assembly is not designed by its class and wheel track. This should 12.7 be looked into corrective action. 12.9 Adequacy of literature: Service manual parts catalogues of trailer were not provided. However, operation manual and parts catalogue shall be brought out in Hindi and other regional languages also as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel. TESTING AUTHORITY: D.C. MOULI AGRICULTURAL ENGINEER P.KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C) 13. Applicant Comments Ok. No specific comments

SOUTHERN REGION FARM MACHINERY TRAINING & TESTING INSTITUTE, ANANTAPUR, (A.P.)

TRACTOR TRAILER

RASOOL ENGINEERING WORKS REW 5 TNE

The dimensions of ring type hitch does not meet, in full, the requirement of

IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective

The dimensions of various components of axle assembly do not conform, in

COMMERCIA (ICT)

Page 27 of 27

T-132/1517

12.4

12.5

action