

व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक)
COMMERCIAL TEST REPORT
(INITIAL)

संख्या/No: T-134/1523
माह/Month: July, 2023
Validity: 30.06.2030

THIS TEST REPORT IS VALID UPTO 30.06.2030



TRACTOR TRAILER
SRI VIJAYA DURGA AGRO INDUSTRIES SVDAI 3 TON



भारत सरकार

Government of India



कृषि एवं किसान कल्याण मंत्रालय
Ministry of Agriculture and Farmers Welfare

कृषि एवं किसान कल्याण विभाग
Department of Agriculture and Farmers Welfare

दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान
Southern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, गार्लदिन्ने - 515 731, जिला: अनंतपुर (आं. प्र.)
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: <http://srfmtti.dacnet.nic.in/>

E-mail: fmti-sr@nic.in

Tele. 08551-286441

T-134/1523	TRACTOR TRAILER	COMM (10
	SRI VIJAYA DURGA AGRO INDUSTRIES SVDAI 3 TON THIS TEST REPORT IS VALID UPTO 30.06.2030	

Manufacturer : M/s. Sri Vijaya Durga Agro Industries
Flat No.- 83, M G Auto Nagar, Kotha
Panchayat, Proddatur, YSR Dis
Kadapa(Cuddapah), Andhra Pradesh, 516360, In

Applicant : The Manufacturer

TRACTOR TRAILER
SRI VIJAYA DURGA AGRO INDUSTRIES SVDAI 3 TON

Report No. : T-134/1523 Month: July Year: 2023



Government of India
Ministry of Agriculture and Farmers Welfare
Department of Agriculture and Farmers Welfare
Southern Region Farm Machinery Training and Testing Institute
Tractor Nagar, Garladinne- 515 731, District: Anantapur (A.P.)
[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <http://srfimtti.dacnet.nic.in/>

E-mail: fimti-sr@nic.in

T-134/1523	TRACTOR TRAILER			COMMERCIAL (ICT)
	SRI VIJAYA DURGA AGRO INDUSTRIES SVDAI 3 TON			
THIS TEST REPORT IS VALID UPTO 30.06.2030				
	the manufacturer			
8	Overall length, mm	2000 to 4100 to be checked	4250	Conforms
9	Overall width, mm	900 (min) to be checked	1510	Conforms
10	Overall height, mm	600 (min)	1400	Conforms
11	Min, ground clearance, (mm)	300	365	Conforms
12	Marking /labeling of machine	The labeling plate should be riveted on the body of machine having name and address of manufacturer, country of origin, make, model, month & year of manufacturer, serial number, size, required size of prime mover (kW), weight (Kg)	Provided	Conforms

12. SUMMARY OF OBSERVATIONS, COMMENTS AND RECOMMENDATION

- 12.1 The specification of trailer does not conform in full, to the IS 8213:2020. This should be looked into for corrective action.
- 12.2 The dimensions of hydraulic tipping cylinder do not meet, in full to the requirement of IS 12371:2019. This should be taken care for corrective action
- 12.3 The dimensions of ring type hitch does not meet as per the requirement of IS 11270:1980 (Reaffirmed 2019). This should be taken care for corrective action.
- 12.4 The Slow Moving Vehicle Emblem not provided. These should be provided.




T-134/1523	TRACTOR TRAILER	COMMERCIAL (ICT)
	SRI VIJAYA DURGA AGRO INDUSTRIES SVDAI 3 TON	
THIS TEST REPORT IS VALID UPTO 30.06.2030		



12.5 Adequacy of literature:

Service manual parts catalogues of trailer were not provided. However, operation manual and parts catalogue should be brought out in Hindi and other regional languages also as per IS 8132: 1999 (Reaffirmed 2019) for the sake of user & technical personnel.

TESTING AUTHORITY:

D.C. MOULI AGRICULTURAL ENGINEER	 
P.KAMALABAI SENIOR AGRICULTURAL ENGINEER/DIRECTOR(I/C)	

13. APPLICANT COMMENTS.

S.NO	PARA NO	Comments
1	12.1	We will do necessary action to meet parameters to the IS 8213:2020.
2	12.2	We will take action on dimensions of hydraulic tipping cylinder to meet, in full to the requirement of IS 12371:2019.
3	12.3	We will do the action to dimensions of ring type hitch to meet, in full, the requirement of IS 11270:1980 (Reaffirmed 2019).
4	12.4	We will provide slow moving emblem in future products
5	12.5	We will provide