# व्यावसायिक परीक्षण रिपोर्ट (प्रारंभिक) COMMERCIAL TEST REPORT (INITIAL)

संख्या/No: IMP-533/1124 माह/Month: February, 2020

Validity: 31.01.2023



# MASCHIO GASPARDO VIRAT LIGHT 145 ROTAVATOR (Tractor Mounted, PTO Operated)



#### भारत सरकार

#### **Government of India**

कृषि एवं किसान कल्याण मंत्रालय Ministry of Agriculture and Farmers Welfare कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare दक्षिणी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान Southern Region Farm Machinery Training and Testing Institute ट्रैक्टर नगर, गार्लदिन्ने-515 731, जिला: अनंतपुर (आं. प्र.)

Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Website: http://srfmtti.dacnet.nic.in/

E-mail: fmti-sr@nic.in Tele./FAX: 08551-286441

IMP-533/1124

# MASCHIO GASPARDO VIRAT LIGHT 145 ROTAVATOR (Tractor Mounted, PTO Operated)

COMMERCIAL (ICT)

Manufacturer : M/s. Maschio Gaspardo India Pvt. Ltd.,

Plot No. F-27 MIDC, Village - Karegaon,

Tal. Shirur, Ranjangaon, Dist-Pune - 412 220, **India**.

Applicant : The Manufacturer

# MASCHIO GASPARDO VIRAT LIGHT 145 ROTAVATOR (Tractor Mounted, PTO Operated)

Report No.: IMP-533/1124 Month: February Year: 2020



#### **Government of India**

Ministry of Agriculture and Farmers Welfare Department of Agriculture, Cooperation and Farmers Welfare Southern Region Farm Machinery Training and Testing Institute Tractor Nagar, Garladinne-515 731, District: Anantapur (A.P.)

[An ISO 9001:2015 CERTIFIED INSTITUTE]

Telephone: 08551-286441

Website: <a href="http://srfmtti.dacnet.nic.in/">http://srfmtti.dacnet.nic.in/</a>

E-mail: <a href="mailto:fmti-sr@nic.in">fmti-sr@nic.in</a>

IMP-533/1124

# MASCHIO GASPARDO VIRAT LIGHT 145 ROTAVATOR (Tractor Mounted, PTO Operated)

COMMERCIAL (ICT)

12.8	CATEGORY OF BREAKDOWNS/DEFECTS				
	Category of breakdown	Category (Evaluative/ non- evaluative)	Requirements	As observed	Whether meets the requirem ent (Yes/No
i)	Critical breakdown	Evaluative	No critical breakdown	None	Yes
ii)	Major breakdowns	Evaluative	Not more than one and neither of them should be repetitive in nature	None	Yes
iii)	Minor breakdowns	Evaluative	Not more than three and frequency of each should not be more than two	None	Yes
iv)	Total breakdowns	Evaluative	In no case, the total number of breakdowns should exceed four, that is (1 major+3 minor) or 4 minor breakdowns	Nil	Yes

#### 13. SUMMARY OF OBSERVATIONS, COMMENTS & RECOMMENDATIONS

- No ingress of dust and water/mud in primary reduction gear box, secondary reduction gear box, and rotary axle bearing cap was observed.
- Provisions for breather cap, oil level dipstick in primary and secondary gearbox are provided.
- The specification of implement hitch is not conforming in full to the IS 4468 (Pt-I):1997. This should be looked into for corrective action.
- Dimensions of PIC is not conforming in full to IS 4931:1995. This should be looked into for corrective action.
- Dimensions of PIC yoke is not conforming in full to IS 4931:1995. This should be looked into for corrective action.

# MASCHIO GASPARDO VIRAT LIGHT 145 ROTAVATOR (Tractor Mounted, PTO Operated)

COMMERCIAL (ICT)

- 13.6 Safety device is provided in rotavator propeller shaft.
- 13.7 Provision for parking stand is provided in rotavator.

# 13.8 Adequacy of literature:

Operator's manual, service manual and parts catalogue of the Rotavator in English were provided in single booklet form for reference during the test. However, this should be brought out in Hindi and other regional languages as per IS 8132:1999 (Reaffirmed 2004) for the sake of user & technical personnel.

### **TESTING AUTHORITY:**

B.N. DIXIT AGRICULTURAL ENGINEER	BC
Dr. P.P. RAO DIRECTOR	P.P. Ras

#### 14. APPLICANT'S COMMENTS

Para No.	Our reference	Applicant's comments
14.1	13.3	Required corrective action shall be taken
14.2	13.4	Required corrective action shall be taken
14.3	13.5	Required corrective action shall be taken
14.4	13.8	Mentioned literature shall be introduced in Hindi and other regional languages.